## RECEIVED

Revised 06/02

CORRES. CONTROL INCOMING LTR NO.

Department of Energy

, 2007 JUL -3 A 9 53

ROCKY FLATS FIELD OFFICE
10808 HIGHWAY 93, UNIT CORRESPONDENCE
GOLDEN, COLORADO 80403-8200 CONTROL

02-DOE-01014

DUE DATE ACTION

DIST. BOGENBERGER, V JUL 0 2 2002

Mr. Steven H. Gunderson
Rocky Flats Cleanup Agreement Project Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, CO 80222-1530

Dear Mr. Gunderson:

Please find attached the Pre-demolition Survey Report for buildings 875, 875 tunnel and 880. They are submitted for consultative review. The buildings are free releasable except the deluge tank and associated piping. It is the Site's intention to proceed with demolition immediately as CDPHE has provided feedback as to the acceptability of this report and DOE finds the report to meet the requirements to proceed with demolition.

The floor drains will be characterized and properly dealt with by either removal or flushing depending on the results of the characterization.

The two sumps in proximity to building 875 will be further characterized and the results and disposition documented in the closeout report.

Questions can be directed to Steve Tower, RFFO, AMP at (303) 966-2133.

Idseph A. Legare
Assistant Manager

for Environment and Stewardship

COR. CONTROL	X	X
ADMN. RECORD	X	
PATS/130		

KGHLER R

PARSONS D

NESTA S

BROOKSZ

Attachment

Reviewed for Addressee Corres, Control RFP cc:

S. Tower, AMP

K. Kehler, K-H RISS D&D

D. Parsons, K-H RISS D&D

S. Nesta, K-H RISS Env

Tim Rehder, EPA Region VIII

T130G Administrative Record

DOE ORDER #

Ref. Ltr. #

5400.1



ADMIN RECORD

B886-A-000062